

1.0 Product and Company Identification			
Identification of the p	reparation	HP LaserJet Car	tridge C9733A
Company Identification	Ē	Hewlett-Packard Cor 1311 Chinden Boul Boise, Idaho 83714 Jnited States	
Emergency telephone number Hewlett-Packard Health Effects Line		1-800-457-4209 (USA and Canada) Intl: +1-503-494-7199 (all other areas) Singapore: +001-800-332-13321	
General information telephone number		1-208-323-2551 (USA and Canada) Intl: +1-208-323-2551 (all other areas)	
Local Contact Information		reland Liffey Park Technolo Barnhall Road Leixlip Kildare, Ireland Phone: 01 6150000 Jnited Kingdom Hewlett-Packard, Ltd Cain Road, Amen Co Bracknell, Berkshire, Phone: 1344 36-000	b, Co. I. prner RG12 1HN
	Hazard Rating	US NFPA/HMIS	-
	Health	1	4
	Flammability	1	-
	Instability/Reactivity Special	0 N/A	4
	Special		1

## 2.0 Composition/Information on Ingredients

This product is a magenta toner preparation that is used in Hewlett-Packard Color LaserJet 5500 series printers.

Component/Substance	CAS Number	EU Number	% by Weight	Risk
				Phrases
Styrene Acrylate	-	-	75 - 85	-
Copolymer				
Wax	-	-	5 - 10	-
Pigment	-	-	1 - 6	-
Amorphous Silica	-	-	1 - 2	-



# 3.0 Hazard Identification

The preparation is not classified	according to EU Directive 1999/45/EC
Routes of Exposure	Inhalation, Ingestion, skin and eyes.

	initial atom, ingestion, skin and eyes.
Acute Health Hazards	
Inhalation:	Respiratory tract irritation may occur with exposure to large amounts of dust.
Ingestion:	Low acute toxicity. Ingestion is a minor route of entry for intended use of this product.
Skin: Eyes:	Unlikely to cause skin irritation. May cause transient slight irritation.
Chronic Health Hazards	Prolonged inhalation of excessive amounts of any dust may cause lung damage. Use of this product as intended does not result in inhalation of excessive amounts of dust.
Carcinogenicity	Refer to section 11.

## 4.0 First Aid Measures

Inhalation:	Move person to fresh air immediately. If symptoms occur, consult a physician.
Ingestion:	Rinse mouth out with water. Drink one to two glasses of water. If symptoms occur, consult a physician immediately.
Skin:	Wash affected areas with soap and water. If irritation persists, consult a physician.
Eyes:	Do not rub eyes. Immediately flush with large amounts of clean, lukewarm water (low pressure) for at least 5 minutes or until particles are removed. If irritation persists, consult a physician.

## 5.0 Fire Fighting Measures

Extinguishing media	CO <sub>2</sub> , water, dry chemical
Unsuitable Extinguishing Media	None
Special Firefighting Procedures	None
•	Like most organic material in powder form, toner can form explosive dust-air mixtures when finely dispersed in air.
Auto-ignition temperature	Not available
Flashpoint (method)	Not applicable
Hazardous Combustion Products	CO <sub>2</sub> , CO



### 6.0 Accidental release measures

Spill or leak procedures	Avoid breathing dust. Minimize the release of particles. Slowly sweep the material into a bag or other sealed container. Clean remainder with a damp cloth or vacuum cleaner. If a vacuum is used, the motor must be rated as dust explosion-proof. Fine powder can form explosive dust-air mixtures. Dispose of waste toner in accordance with local requirements.
Environmental precautions	Do not discharge into drains (See also Section 13, Disposal Considerations).

## 7.0 Handling and Storage

Keep material out of reach of children. Avoid inhalation of dust and contact with eyes. Use with adequate ventilation. Keep away from excessive heat, sparks, and open flames.
Keep out of the reach of children. Keep container closed and store at room temperature. Keep away from strong oxidizers.

## 8.0 Exposure control/ personal protection

Exposure Limit Values	
USA OSHA (TWA/PEL):	
	5 mg/m <sup>3</sup> (Respirable Fraction)
ACGIH (TWA/TLV):	10 mg/m <sup>3</sup> (Inhalable Particulate)
	3 mg/m <sup>3</sup> (Respirable Particulate)
TRGS 900 (Luftgrenzwert):	10 mg/m3 (Einatembare Partikel)
	3 mg/m3 (Alveolengängige Fraktion)
	USA OSHA (TWA/PEL), ACGIH (TWA/TLV)
Amorphous Silica	20 mppcf 80(mg/m <sup>3</sup> )/%SiO <sub>2</sub> , None established
Exposure Controls	
Respiratory protection	Not required under intended use.
Ventilation	Good general ventilation should be sufficient under
	intended use.
Protective gloves	Not required under intended use.
Eye protection	•
Other protective equipment	Not required under intended use.

## 9.0 Physical and chemical properties

pHNot applicableBoiling pointNot applicableFlash pointNot applicableMelting point100 – 150°C (Softening Point)



Flammability	Non-flammable solid (according to test methods of EU Directive 92/69/EEC, A10 Flammability (Solids))
Explosive properties	Toner material, like most organic material in powder
• • • • • •	form, is capable of creating a dust explosion.
Oxidizing properties	No data available
Vapor Pressure	Not applicable
Specific gravity (H <sub>2</sub> O=1)	1.0 - 1.2
Solubility in water	Negligible
Solubility in organic	Partially soluble in toluene and xylene.
solvents	
Partition coefficient	Not applicable
Viscosity	Not applicable
Vapor density	Not applicable
Evaporation rate	Not applicable
Physical state	Fine powder
Color	Magenta
Odor	Slight plastic odor
Other	Decomposition Temperature: >200 ° C
Other	

# 10.0 Stability and reactivity

Stability	Stable under normal storage conditions
Incompatibilities	Strong oxidizers
Hazardous decomposition	CO <sub>2</sub> , CO
products	
Hazardous polymerization	Will not occur

# 11.0 Toxicological information

Refer to Section 3 for potential heath effects and Section 4 for first aid measures

Inhalation: Ingestion:	LC <sub>50</sub> :inh-rat>5mg/L/4 hrs., not harmful. LD <sub>50</sub> :orl-rat>2000 mg/kg, not harmful.
Eye Contact:	Not classified as irritant, according to OSHA Hazard Communication Standard (HCS) and EU Directive 67/548/EEC.
Skin Contact:	Not classified as irritant, according to OSHA Hazard Communication Standard (HCS) and EU Directive 67/548/EEC.
Chronic Toxicity:	No data available.
Sensitization:	Not classified as a sensitizer according to EU Directive 67/548/EEC and OSHA HCS (US).
Mutagenicity:	Negative, does not indicate mutagenic potential (Ames Test: Salmonella typhimurium)
Carcinogenicity:	Not a known or suspected carcinogen according to any IARC Monograph, NTP, OSHA Regulations (USA), EU Directive, or Proposition 65 (California).



**Reproductive Toxicity:** Not classified as toxic according to EU Directive 67/548/EEC, California Prop. 65, or DFG (Germany).

### 12.0 **Ecological Information**

No data available for ecological and wastewater treatment (sewage) systems. Avoid spills and dispose of in accordance with applicable laws and regulations.

#### 13.0 **Disposal considerations**

Do not put toner or toner cartridge into fire; heated toner may cause severe burns. Do not shred toner cartridge, unless dust-explosion prevention measures are taken. Finely dispersed particles may form explosive mixtures in air. Dispose of in compliance with federal, state, and local regulation.

#### 14.0 **Transportation information**

Not a regulated article under DOT, IATA, ADR, or RID

UN Number	None
Class	None
Proper Shipping Name	None
Packing Group	None
Special Precautions	None

### 15.0 **Regulatory information**

US EPA TSCA Inventory US EPA TSCA 12(b) US California Proposition 65 EU Notification	All ingredients are listed on TSCA inventory None None All components in this product are compliant with EU Chemical Inventory regulations.
EU Hazard Label (1999/45/EC): Special Precautions under 1999/45/EC, Annex V	Product does not require a label under 1999/45/EC
USA Labeling Symbol Hazard Warning Safety Advice Hazardous Component(s)	Not required Not required Not required None

16.0 Other information

> Date Prepared: September 23, 2002 **HP-DMS Document Control** Number:



Revision Information: None

EU Information

This MSDS was prepared in compliance with EU Directive 91/155/EEC as amended by 2001/58/EC and USA OSHA Hazard Communications regulations (29CFR1910:1200).

DISCLAIMER: This Material Safety Data Sheet (MSDS) is provided without charge to customers of Hewlett-Packard. Data is the most current known to Hewlett-Packard at the time of preparation of this MSDS and is believed to be accurate. It should not be construed as guaranteeing specific properties of the products as described or their suitability for a particular application.